

<b>Stream Survey, 12 Mile Creek, July 16, 2003</b>									
<b>Latitude:</b> N39 57.620									
<b>Longitude:</b> W84 19.431									
	<b>Depth</b>	<b>Width</b>	<b>T</b>	<b>pH</b>	<b>DO</b>	<b>Turbidity</b>	<b>Velocity</b>	<b>Habitat</b>	<b>Bio Index</b>
	<b>(cm)</b>	<b>(m)</b>	<b>(C)</b>	<b>(SU)</b>	<b>(ppm)</b>		<b>(m/s)</b>	<b>0-200</b>	<b>0-30</b>
<b>Riffle</b>	25.0	6.0	25.0	8.3	6.4	turbid	0.8	130.0	19.0
<b>Pool</b>	21.0	10.0	29.5	7.5	7.5	turbid	0.1	130.0	24.0
<b>Run</b>	56.5	6.0	27.0	8.0	7.3	turbid	1.0	130.0	27.0
<b>Rating</b>								Suboptimal	Good to Excellent